Range NT-4 Location

In SE¼ SW¼ Sec. 13, E½ NW¼ & W½ NE¼ Sec. 24, T-4-S, R-2-E, Tippah County, Miss.

Right (N) end on land of Hines Graves, who removed monument after striking it with equipment. We found the concrete, but w/o metal disk (which he reported was missing when he found concrete), by a lone multiple-trunk dogwood on knoll in cultivated field.

Left (S) end on former Coombs land, now owned by W. E. Childress



Run Left Stansning — to Right Looking downstream to be reversed for plotting.

NT-4 Profile

Sta					
Reversed to original direction ↓					
	2.48	409.63			407.15
	0.09	409.59	0.03	409.60	
30+67			2.54		407.12
30+66					
0+005			3.0	406.7	
30+64 +03			3.3	406.4	
30+59 +08			4.9	404.8	
30+47 +20			5.2	404.5	
30+34 +33			7.2	402.5	
30+27 +40			7.9	401.8	
30+07 +60			9.0	400.7	
29+89 +78			10.7	399.0	
29+78 +89			11.4	398.3	
29+74 +93			14.4	395.3	
29+70 +97			14.9	394.8	
29+67					
1+00			13.3	396.4	
29+63 +04			11.0	398.7	
29+59 +08			11.9	397.8	
29+53 +14			10.4	399.3	
29+49 +18			9.4	400.3	
29+47 +20			9.7	400.0	
T.P.	3.31	404.17	8.89		400.80
29+27 +40			4.8	399.3	
29+07 +1.0			4.3	399.8	
28+87 +80			4.2	399.9	

28'R 43.2

5/28/69 Turner T Dalton Ch Stanford ϕ Happ III

Turned 0° 28' R from trial line

Top Mon. NT-4-L

TBM Knails in NW root 11" pin oak 43.2 E of Mon.

Top mon. NT-4-L

Grd in front of monument

2.5' upstream from two large Black Gums

Top Bank ditch

Fence/Line Lv. pasture, enter corn

Top post stake

cont'd

28+67	404.1		
2+00		4.4	399.7
28+47 +20		4.2	399.9
28+27 +40		4.2	399.9
28+07 +60		4.5	399.6
27+87 +80		4.5	399.6
27+67 3+00		4.4	399.7
27+47 +20		4.2	399.9
27+27 +40		4.3	399.8
27+07 +60		4.8	399.3
27+00 +67		5.0	399.1
26+80 +87		4.8	399.3
26+60 4+07		4.5	399.6
26+40 +27		4.1	400.0
26+20 +47		4.2	399.9
26+00 +67		4.5	399.6
25+80 +87		4.3	399.8
25+60 5+07		4.2	399.9
25+40 +27		4.1	400.0
25+20 +47		5.6	398.5
25+00 +67		4.4	399.7
24+80 +87		4.5	399.6
24+60 6+07		4.7	399.4
24+40 +27		4.6	399.5
24+20 +47		4.7	399.4
24+00 +67		4.7	399.4

field drain

23+80		404.11 (35)			
6+87			4.7	399.4	
T.P.	5.21	404.88 (25)	4.52		399.59 (615)
23+60					
7+07			5.2	399.6	
23+40					
+27			5.5	399.3	
23+20					
+47			5.5	399.3	
23+04					
+63			5.5	399.3	
23+02					
+65			6.1	398.7	
23+00					
+67			6.1	398.7	
22+80					
+87			5.8	399.0	
22+60					
8+07			5.9	398.9	
22+40					
+27			5.9	398.9	
22+20					
+47			5.9	398.9	
22+00					
+67			5.9	398.9	
21+80					
+87			5.9	398.9	
21+60					
9+07			5.8	399.0	
21+40					
+27			5.6	399.2	
21+20					
+47			5.8	399.0	
21+00					
+67			5.5	399.3	
20+80					
+87			5.4	399.4	
20+67					
10+00			5.4	399.4	
20+60					
+07			5.4	399.4	
20+40					
+27			4.7	400.1	
20+20					
+47			3.5	401.3	
20+00					
+67			2.8	402.0	
19+80					
+87			2.5	402.3	
			2.32	402.48 (505)	

top of spoil-edge of field ditch

TOP

TOP BMS

	Cont'd				
		404.88 25			
19+67					
11+00			2.7	402.1 ✓	
19+60 +07			3.7	401.1 ✓	
19+49 +18			5.5	399.3 ✓	
19+45 +22			8.9	395.9 ✓	
19+30 +37			14.9	389.9 ✓	
19+26 +41			15.6	389.2 ✓	
19+22 +45			17.6	387.2 ✓	
19+20 +47			18.0	386.8 ✓	
19+13 +54			18.0	386.8 ✓	
19+03 +64			17.7	387.1 ✓	
18+94 +73			17.6	387.2 ✓	
18+88 +79			16.1	388.7 ✓	
18+84 +83			13.2	391.6 ✓	
18+76 +91			10.6	394.2 ✓	
18+73 +94			6.6	398.2 ✓	
18+67 12+00			6.2	398.6 ✓	
18+60 +07			6.1	398.7 ✓	
18+40 +27			3.5	401.3 ✓	
18+28 +39			2.8	402.0 ✓	
18+20 +47			3.2	401.6 ✓	
18+00 +67			3.8	401.0 ✓	
17+80 +87			5.2	399.6 ✓	
17+60 13+07			6.7	398.1 ✓	
TP			6.60		398.28 ✓ 25
		4.04	402.24 ✓ 65		

Top lt. Bank - 20' downstream from lt. lateral

O.E. & surface - North Tippah ditch, dug about 6 yrs ago.

W.E. & W.S.

Top of Bank - North Tippah ditch

Top of Spoil Bank

Pile Field

17+40	402.24 65		
13+27		4.9	397.34
17+20 47		4.9	397.34
17+00 67		5.0	397.32
16+80 87		5.0	397.32
16+67 14+00		4.8	397.54
16+60 07		5.0	397.32
16+40 27		4.8	397.54
16+20 47		4.5	397.88
16+00 67		4.6	397.76
15+80 87		4.7	397.65
15+67 15+00		4.5	397.88
15+60 07		4.4	397.98
15+40 27		4.5	397.76
15+20 47		4.5	397.87
15+00 67		4.7	397.56
14+80 87		4.7	397.56
14+60 16+07		5.7	396.56
14+40 27		5.0	397.32
14+20 47		5.2	397.10
14+00 67		5.3	396.79
13+80 87		5.5	396.47
13+60 17+07		4.7	397.56
13+40 27		4.4	397.98
13+20 47		4.3	398.09
13+00 67		4.2	398.10

Shallow drain of field boundary, crossed ± 45°. Approx. Enter cotton

N-S 1/4 Sec. Line

		402.24 45			
12+80				8.0	
12+60 87			4.3	397.9	
12+40 07			4.6	397.6	
12+33 27			4.1	398.2	
12+26 34			2.7	399.6	
12+23 41			4.9	397.4	
12+16 44			9.5	392.8	
12+12 51			13.2	389.1	
12+09 55			13.0	389.3	
12+02 58				388.4	
11+98 65				388.1	
11+92 69				389.3	
11+89 75			12.6	389.7	
11+80 78			6.3	395.9 6.0	
11+67 87			4.6	397.7	
11+60 19+00			3.6	398.7	
			3.9	398.4	
			3.5	398.8	
			3.68		398.58 85 ✓
	3.94	402.58 25 ✓			
11+40 27			4.2	398.3 ✓	
11+20 47			4.3	398.2 ✓	
11+00 67			4.1	398.4 ✓	
10+80 87			4.0	398.5 ✓	
10+60 20+07			4.1	398.4 ✓	
10+40 27			4.1	398.4 ✓	

Lv. cotton

Top spoil - pushed up from land clearing; channel not dredged

Top L Bk old channel No. Tippah Creek. One ft downstream from blazed 6" hickory.

W.E.

W.S.

0.9 water

1.2 "

0.0 "

Top R Bk. old channel

Lv brush, enter cult. field

		402.58 25		
10+20 47			4.1	398.4
10+00 67			4.2	398.3
9+80 87			4.4	398.1
9+60 21+07			4.5	398.0
9+40 27			4.6	397.9
9+20 47			4.6	397.9
9+00 67			4.7	397.8
8+80 87			4.7	397.8
8+60 22+07			4.7	397.8
8+40 27			4.7	397.8
8+20 47			4.6	397.9
8+00 67			4.7	397.8
7+80 87			4.7	397.8
7+60 23+07			4.6	397.9
7+40 27			4.7	397.8
7+30 37			4.6	397.9
7+20 47			4.1	398.4
7+09 58			6.7	395.8
7+06 61			8.0	394.5
7+02 65			7.8	394.7
7+00 67			5.8	396.7
6+90 77			5.2	397.3
6+86 81			4.0	398.5
6+79 88			0.6	401.9
6+76 91			05	402.0

HI

Enter brush

Spoil bank

Ditch - crossing at ± 45° (Embru Creek @ topographic map, but Embry Creek now diverted E along N side this field to old channel N. Tippah)

"

Top spoil bank

6+67		402.5$^{35}_{8}$			
24+00			3.5	399.0 ✓	
			3.22		399.2$^{30}_{8}$^{5} ✓
Instr. at 26+87	3.15	402.4^{55}			
6+60 07			4.7	397.7^{5}	
6+51 16			4.5	397.9^{5}	
6+40 27			5.2	397.2^{5}	
6+20 47			5.2	397.2^{5}	
6+00 67			5.4	397.0^{5}	
5+80 87			5.4	397.0^{5}	
5+60 25+07			5.4	397.0^{5}	
5+40 27			5.2	397.2^{5}	
5+20 47			5.1	397.3^{5}	
5+00 67			5.1	397.3^{5}	
4+80 87			5.2	397.2^{5}	
4+60 26+07			5.2	397.2^{5}	
4+40 27			5.1	397.3^{5}	
4+20 47			5.1	397.3^{5}	
4+00 67			5.0	397.4^{5}	
3+80 87			4.9	397.5^{5}	
3+60 27+07			5.0	397.4^{5}	
3+40 27			4.7	397.7^{5}	
3+20 47			4.7	397.7^{5}	
3+00 67			4.5	397.9^{5}	
2+87 80			4.0	398.4^{5}	
2+80 87			3.9	398.5^{5}	

TPon axe

Enter cotton

H.I.

Lv. cotton field, enter brush

		402.55			
2+60			3.4	399.05	
28+07			3.4	399.05	
2+47 20			3.7	398.75	
2+44 23			3.5	398.95	
2+39 28			3.5	398.95	
2+33 34			3.34		399.59
	8.76	408.75	7.55	400.35	
2+33 28+34			8.9	399.0	
2+20 47			8.7	399.2	
2+00 67			8.5	399.4	
1+80 87			7.3	400.6	
1+60 29+07			6.2	401.7	
1+40 27			4.9	403.0	
1+20 47			4.0	403.9	
1+00 67			2.8	405.1	
0+80 87			1.9	406.0	
0+60 30+07			1.1	406.8	
0+40 27			0.65	407.22	
0+20 47			0.1	407.8	
0+01 66			8.41		399.54
					399.44
					0.00

Ditch

Grd at new pipe on F/L. Enter bean field

TPon axe at 28+20

Top new pipe NT-4-RX at F/L, 6" E of T/post, 15" N35W. from 9" trunk of triple-trunk Ash

$= \frac{23}{5056} = 0.00750 = \text{Tan } 0°25'48"$

23' R. (E) of trial line, Passed 150' S56E from long Top stake on F/L Sta 28+22.5 of trial line, p.26 large dogwood tree

Ref. p. 26

Closure.